Bode Diagram

Frequency Response

- Frequency Response is the steadystate behavior of the system when forced by a sinusoidal input.
- Consider a first order system

$$G(s) = \frac{C(s)}{R(s)} = \frac{K_p}{\tau s + 1}$$

• Let us assume that this process is subjected to a sinusoidal input

$$u(t) = A\sin\omega t$$

where A is the amplitude and ω is the frequency

• Laplace transform of the input gives

$$U(s) = \frac{A\omega}{s^2 + \omega^2}$$

- hence, the Laplace transform of the output becomes $C(s) = \frac{K_p}{\tau s + 1} \frac{A\omega}{s^2 + \omega^2}$
- expanded into fractions

$$C(s) = \frac{B_1}{s+1/\tau} + \frac{B_2}{s+j\omega} + \frac{B_3}{s-j\omega}$$

• inverse Laplace transform, take $t \rightarrow \infty$,

$$u(t \to \infty) = \frac{AK_p}{\omega^2 \tau^2 + 1} \sin \omega t - \frac{AK_p}{\omega^2 \tau^2 + 1} \cos \omega t$$

• Or

$$a_1 \sin \omega t + a_2 \cos \omega t = a_3 \sin(\omega t + \varphi)$$

• where $a_3 = \sqrt{a_1^2 + a_2^2}, \varphi = \tan^{-1}\left(\frac{a_2}{a_1}\right)$
• Therefore, $u(t \to \infty) = \frac{AK_p}{\sqrt{\omega^2 \tau^2 + 1}} \sin(\omega t + \varphi)$
 $\varphi = \tan^{-1}(-\omega\tau)$

- It can be seen that the response to a sinusoidal input signal is a sinusoidal signal with the same frequency but a different angle. The output signal lags behind the input signal by an angle φ, which depends on the frequency ω.
- The ratio between the amplitude of the input sine wave and the output sine wave, called amplitude ratio, K_{n}

$$AR = \frac{\kappa_p}{\sqrt{\omega^2 \tau^2 + 1}}$$

Substitution of s = jω in the transfer function G(s) results in a transfer function in the frequency domain G(jω). Then the magnitude is equal to the amplitude ratio AR:

$$AR = \left| G(j\omega) \right|$$

• and the phase angle or argument is equal to:

$$\varphi = \arg[G(j\omega)]$$

• *G*(*jω*) is a complex number, it can therefore be represented by a real and imaginary part:

$$G(j\omega) = \operatorname{Re}[G(j\omega)] + j\operatorname{Im}[G(j\omega)]$$

• for which:

$$AR = |G(j\omega)| = \sqrt{(\operatorname{Re}[G(j\omega)])^2 + (j\operatorname{Im}[G(j\omega)])^2}$$
$$\varphi = \arg[G(j\omega)] = \tan^{-1} \frac{\operatorname{Im}[G(j\omega)]}{\operatorname{Re}[G(j\omega)]}$$

• When substituting $s = j\omega$ into

$$G(j\omega) = \frac{C(j\omega)}{R(j\omega)} = \frac{K_p}{\tau(j\omega) + 1} \frac{(-\tau(j\omega) + 1)}{(-\tau(j\omega) + 1)}$$

$$=\frac{K_p}{\omega^2\tau^2+1}-j\frac{K_p\omega\tau}{\omega^2\tau^2+1}$$

• **Therefore**, $magnitude = AR = \frac{K_p}{\sqrt{\omega^2 \tau^2 + 1}}$

phase angle
$$\varphi = \tan^{-1}(-\omega\tau)$$

• A transfer function is often a combination of subtransfer functions, consisting of numerator and denominator terms:

$$G(j\omega) = \frac{G_1(j\omega)G_2(j\omega)\cdots G_n(j\omega)}{G_{n+1}(j\omega)G_{n+2}(j\omega)\cdots G_m(j\omega)}$$

• It can easily be shown that $AR = |G_1(j\omega)G_2(j\omega)\cdots| = |G_1(j\omega)||G_2(j\omega)|\cdots$

 $\varphi = \arg[G_1(j\omega)G_2(j\omega)\cdots] = \arg[G_1(j\omega)] + \arg[G_2(j\omega)] + \cdots$

• For inverse transfer functions the amplitude ratio and phase angle can be derived from the property: $AR = \left| \frac{1}{G(j\omega)} \right| = \frac{1}{|G(j\omega)|} \qquad \varphi = \arg \frac{1}{G(j\omega)} = -\arg [G(j\omega)]$

Therefore,

$$AR = |G(j\omega)| = \frac{\prod_{i=1}^{n} |G_i(j\omega)|}{\prod_{j=n+1}^{m} |G_j(j\omega)|}$$

$$\varphi = \arg[G(j\omega)] = \sum_{i=1}^{n} \arg[G_i(j\omega)] - \sum_{j=n+1}^{m} \arg[G_j(j\omega)]$$

Bode Diagram

- The graphs in which the amplitude ratio and phase shift are plotted as a function of the frequency ω, are called Bode diagrams.
- In the Bode plot, log(*AR*) and *φ* are shown as a function of *ω*. In case of the first-order process,

$$magnitude = AR = \frac{K_p}{\sqrt{\omega^2 \tau^2 + 1}}$$

• **Or**
$$\log(AR) = \log(K_p) - \frac{1}{2}\log(\omega^2 \tau^2 + 1)$$

- thus log (AR) becomes a linear function of log($\omega \tau$) with a slope of -1.
- In case of $\omega \ll 1/\tau$: $\log(AR) = \log(K_p) + \frac{1}{2}\log(1) = \log(K_p)$ thus the gain of the process is independent of the frequency ω .
- In case $\omega = 1/\tau$:


$$\log(AR) = \log(K_p) + \frac{1}{2}\log(2)$$

phase angle
$$\varphi = \tan^{-1}(-\omega\tau)$$

- In case of $\omega >> 1/\tau$: phase angle $\varphi = \tan^{-1}(\infty) = -90^{\circ}$
- In case $\omega \ll 1/\tau$: phase angle $\varphi = \tan^{-1}(0) = 0^{\circ}$
- In case $\omega = 1/\tau$:

phase angle
$$\varphi = \tan^{-1}(1) = -45^{\circ}$$

Bode diagram of a first-order process



Second-order Non-interacting System

$$G(s) = \frac{K_1}{(\tau_1 s + 1)} \frac{K_2}{(\tau_2 s + 1)}$$

• the amplitude ratio and phase angle become:

$$AR = |G(j\omega)| = \frac{\prod_{i=1}^{n} |G_i(j\omega)|}{\prod_{j=n+1}^{m} |G_j(j\omega)|} \qquad AR = \frac{K_1 K_2}{\sqrt{\omega^2 \tau_1^2 + 1} \sqrt{\omega^2 \tau_2^2 + 1}}$$
$$\varphi = \arg[G(j\omega)] = \sum_{i}^{n} \arg[G_i(j\omega)] - \sum_{j=n+1}^{m} \arg[G_j(j\omega)]$$
$$\varphi = \tan^{-1}(-\omega\tau_1) + \tan^{-1}(-\omega\tau_2)$$

Underdamped Second-order System

• Second-order System

$$G(s) = \frac{K_p}{\tau^2 s^2 + 2\zeta\tau s + 1}$$

• Substituting $s = j\omega$ into equation and rearranging results in:


$$G(j\omega) = \frac{K_p}{\left(1 - \omega^2 \tau^2\right) + 2j\zeta\omega\tau}$$

• Recall:

$$AR = |G(j\omega)| = \sqrt{(\operatorname{Re}[G(j\omega)])^2 + (j\operatorname{Im}[G(j\omega)])^2}$$
$$\varphi = \arg[G(j\omega)] = \tan^{-1} \frac{\operatorname{Im}[G(j\omega)]}{\operatorname{Re}[G(j\omega)]}$$

• Therefore, $G(j\omega) = \frac{K_p}{(1-\omega^2\tau^2)+2\,j\zeta\omega\tau} \frac{(1-\omega^2\tau^2)-2\,j\zeta\omega\tau}{(1-\omega^2\tau^2)-2\,i\zeta\omega\tau}$ $=\frac{K_p}{\left(1-\omega^2\tau^2\right)^2+\left(2\zeta\omega\tau\right)^2}\left[\left(1-\omega^2\tau^2\right)-2j\zeta\omega\tau\right]$ $AR = \frac{\kappa_p}{\sqrt{\left(1 - \omega^2 \tau^2\right)^2 + \left(2\zeta\omega\tau\right)^2}}$ $\varphi = \tan^{-1} \left(-\frac{2\zeta \omega \tau}{1-\omega^2 \tau^2} \right)$

Bode diagram for second-order under-damped process



• On the Bode magnitude plot, decibels are used, defined as:


$$a_{dB} = 20\log_{10} a$$
, decibels or dB

• The log-magnitude curve for a constant gain *K* is a horizontal straight line at the magnitude of

 $20\log_{10} K, dB$

• Integral and derivative factors $(j\omega)^{\mp}$

 $20\log|(j\omega)^{\mp}| = \mp 20\log\omega, \ dB$



Example I


• For the transfer function:

$$H(s) = \frac{100}{s+30}$$

• Step 1: Rewrite the transfer function in proper form. Make both the lowest order term in the numerator and denominator unity. Therefore, the numerator is an order 0 polynomial, the denominator is order 1.

$$H(s) = \frac{100}{30} \frac{1}{\frac{s}{30} + 1} = 3.3 \frac{1}{\frac{s}{30} + 1}$$


- Step 2: Separate the transfer function into its constituent parts.
- The transfer function has 2 components:
 - A constant of 3.3
 - A pole at s=-30



• Step 3: Draw the Bode diagram for each part.

- The constant is the cyan (青色) line (A quantity of 3.3 is equal to 10.4 dB). The phase is constant at 0 degrees.
- The pole at -30 rad/sec is the blue line. It is 0 dB up to the break frequency, then drops off with a slope of -20 dB/dec.
- The phase is 0 degrees up to 1/10 the break frequency (3 rad/sec) then drops linearly down to -90 degrees at 10 times the break frequency (300 rad/sec).

Step 4: Draw the overall Bode diagram by adding up the results from step 3.



Example II

• Bode Diagram for the transfer function:


$$H(s) = 100 \frac{s+1}{(s+10)(s+100)} = 100 \frac{s+1}{s^2+110s+1000}$$

• Step 1: Rewrite the transfer function in proper form. Make both the lowest order term in the numerator and denominator unity. The numerator is an order 1 polynomial, the denominator is order 2.

$$H(s) = \frac{100}{10 \cdot 100} \frac{\frac{s}{1} + 1}{\left(\frac{s}{10} + 1\right)\left(\frac{s}{100} + 1\right)} = 0.1 \frac{\frac{s}{1} + 1}{\left(\frac{s}{10} + 1\right)\left(\frac{s}{100} + 1\right)}$$


- Step 2: Separate the transfer function into its constituent parts.
- The transfer function has 4 components:
 - A constant of 0.1
 - A pole at s=-10
 - A pole at s=-100
 - A zero at s=-1

- Step 3: Draw the Bode diagram for each part.
- The constant is the cyan line (A quantity of 0.1 is equal to -20 dB). The phase is constant at 0 degrees.
- The zero at 1 rad/sec is the red line. It is 0 dB up to the break frequency, then rises at 20 dB/dec. The phase is 0 degrees up to 1/10 the break frequency (0.1 rad/sec) then rises linearly to 90 degrees at 10 times the break frequency (10 rad/sec).




- The pole at 10 rad/sec is the green line. It is 0 dB up to the break frequency, then drops off with a slope of -20 dB/dec. The phase is 0 degrees up to 1/10 the break frequency (1 rad/sec) then drops linearly down to -90 degrees at 10 times the break frequency (100 rad/sec).
- The pole at 100 rad/sec is the blue line. It is 0 dB up to the break frequency, then drops off with a slope of -20 dB/dec. The phase is 0 degrees up to 1/10 the break frequency (10 rad/sec) then drops linearly down to -90 degrees at 10 times the break frequency (1000 rad/sec).

Step 4: Draw the overall Bode diagram by adding up the results from step 3.



Stability Analysis

• The phase and gain margins can easily be obtained from the Bode diagram.



• For K = 10 and K = 100, find the phase and gain margins

